

ACTUATOR

WIPER DOOR, STRAIGHT, 1969L-E71

E3736

THIS VACUUM ACTUATOR HAS BEEN TESTED PRIOR TO SHIPMENT. BECAUSE IT IS A NEW UNIT THE ACTUATOR SHAFT WILL NOT MOVE IN AND OUT OF THE CANISTER EASILY BY HAND. IF YOU ARE STILL CONCERNED ABOUT THE WORKING CONDITION OF THIS UNIT, TO TEST CONNECT TO A GOOD VACUUM SOURCE SUCH AS THE POWER BRAKE BOOSTER VACUUM HOSE OF YOUR CAR. (IF POWER BRAKE BOOSTER HOSE IS REMOVED FROM BOOSTER FOR TESTING BE SURE TO RE-INSTALL HOSE BEFORE DRIVING CAR, BRAKE PEDAL PRESSURE WILL INCREASE DRAMATICALLY WITHOUT VACUUM ASSIST.) REVERSE THE RUBBER HOSE TO ONE SIDE OF THE UNIT AND THEN THE OTHER SIDE. YOU WILL SEE THAT THE SHAFT EXTENDS AND RETRACTS PROPERLY. QUESTIONS CALL 805-466-4703.